

United States Steel Corporation Clainton Works 400 State Street Cláirton, PA 15025

RECEIVED

AUG 1 0 2010

3AP20

August 3, 2010

Mr. Ed Peresie Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Mr. Steve Hepler Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject:

USS Reference Number: 10-0318 ACHD Reference Number: 12845 Sulfur Plant Incinerator USS Clairton Works

Gentlemen:

The attached form terminates the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Mark G. Tabler Plant Manager Clairton Works

NOTICE OF PLANNED OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 10-0318 Termination

ACHD Reference Number: 12845

- 2. Date & Time of Breakdown: Date: 07/20/10 Time: 1515 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: Sulfur Plant Incinerator
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: The Sulfur Plant spare incinerator 684 will be unavailable for service to change valves and make associated piping modifications and inspect and repair the refractory as required. The sulfur plant incinerator 684 is a redundant piece of equipment and the 684A incinerator will carry the load.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 The 684A incinerator will carry the load. No environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
 - C. Amount of each type emitted (or likely to be emitted).
 No environmental impact
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

 The 684A incinerator carried the load.
- 10. Facility back in operation Date: 07/30/10 Time: 1300 hours

$\mathscr{A}_{\mathscr{N}} = \{$	
orman War ish Acida	
Signature <u>(((((()/////////((()/</u>)	Date <u>() - () - /() </u>
Can a norm 88 Can with a	

Coleen M. Davis

Senior Environmental Control Engineer Phone: 412-233-1015